ENGINEERING CHANGE NOTICE DART AEROSPACE LTD

Date: 09.09.23 Job No.:	002	269	ADR Yes/No: N	ADR Date:		
Product No.: D130-787			Created By: KB.	Approved By:	-	ECN #: 09- 677
Product Name: TAS Installation			Checked By:	General Manage		NA
			- "}			
	tial / Dat	9	Distribution	Reqd	Resp	Initial / Date
	1000)	DQA / QA Coord	N		
Production Engineering Coord Y EC/DO 189			QC Coordinator	N N	CIAL	Pa
Production Document Control BG BG	19-10	1-3	Marketing	Y	sw S	\$W 09.10.05
Customer Technical Support N /			Customer Order Proces	sing N		. <u> </u>
			J <u>L</u>	ii	1	
Reason for Change: Change P/N LED-41-14-ED-	E05LM t	o LED-42	2-14-ED-E05LM			
Documents Affected: DSI 9481 REV. A MDL-D130-787 REV. D					·	
PARTS MUST COMPLY	,	Υ	PREVIOUS PARTS S	ATISFACTOR	Υ _]
# Quality Assurance Actions	Reqd	Resp		Notes		Complete
Notify Previous Customers	N					
2 Notify Eurocopter France	N		1			1
3	N		·			
	. ''		<u> </u>		·	<u> </u>
# Engineering Actions	Regd	Resp		Notes		Complete
4 Required Documents/Drawings Under Review	Υ					
5 Update Product Compatability Matrix	N					
6 Create Eurocopter Form (FEE)	N					
7 Notify TC / FAA of Change	N					<u> </u>
# Document Control Actions	Reqd	Resp	r	Notes		Complete
8 Move Electronic Files	Kequ	大 大 大 大	· · · · · · · · · · · · · · · · · · ·	totes		09.10.05
9 Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ				09.10.05
10 Update Controlled PDF Files	¥	KJ				09.10.05
11 Update Master Document List (MDL)	Ÿ	KB	MDL-D130-787 REV. D			HA FOR KB OF 18
12 Update Document Record (DR)	Y	KJ	Rey. B			99,10.05
13 Update Product Development Summary	N		100712			
14 Update QSI 021 and/or STC Approval List	N			•		
15 Update Parts / STC Database	N					
16 Update / Verify ARC Database	N					
17 Create / Update Change Record Form	N					
18 Create / Update PPP's	N	_				
19 Update Document Control Database / Laminated Dwgs	N					(A)
20 Update Grey Project Binder	Y	KJ				10,10,05
21 Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	X				09.10:05
22						1
23			l		· · · · · · · · · · · · · · · · · · ·	
Description / Action: ENSURE ALL IN STOCK LED-41-14-ED-E05LM GET NEW UPDATE ROUTING/ESTIMATE/BOM FOR D130-787-013 To				<u>.</u>		
ENSURE ALL D130-787-013 GOING INTO STOCK INCLUD	E LED-4	2-14-ED-	E05LM PER DSI 9481			
TO CORRECT CURRENT PARTS IN STOCK, ORDER LED- TO REPLACE THE SWITCH BODIES: 1) REMOVE LED CAP FROM P/N LED-41-14-ED-BO5L 2) INSTALL LED CAP ON P/N LED-42-14. 3) RELABEL PART LED-42-14-ED-B05LM. 4) RETURN TO STOCK.		ND REPI	LACE CURRENT LED-41-1	4-ED-B05LM SWI	TCH BODIE:	S WITH LED-42-14 SWIT
		FCN Ve	erified & Complete:	P	Date	:09/10/08